




POETRY LIVING

QUICK
TIPS

Millwork



Shrinkage may appear to the millwork, the interior wood trim.

You may notice some joints at the corners of windows, doors and baseboards that will open slightly. This is a normal occurrence due to the drying out process of the home.



Click here to visit
PoetryLiving.com